

Final Report
for
Iowa Department of Transportation
Project HR-504

Galvanized Bridge Deck Reinforcing

by
Chris Anderson
515-239-1392
Office of Materials
Highway Division
Iowa Department of Transportation
Ames, Iowa 50010

December 1992

TECHNICAL REPORT TITLE PAGE

| | |
|--|--|
| 1. REPORT NO. | 2. REPORT DATE |
| HR-504 | December 1992 |
| 3. TITLE AND SUBTITLE | 4. TYPE OF REPORT & PERIOD COVERED |
| Galvanized Bridge Deck Reinforcing | Final Report, 10-66 to 7-92 |
| 5. AUTHOR(S) | 6. PERFORMING ORGANIZATION ADDRESS |
| Chris Anderson, Technician 4 Materials Department | Iowa Department of Transportation 800 Lincoln Way Ames, Iowa 50010 |
| 7. ACKNOWLEDGEMENT OF COOPERATING ORGANIZATIONS | |
| Construction Technology Laboratories, Inc. (CTL) | |
| 8. ABSTRACT | |
| <p>The deterioration of bridge decks due to steel corrosion is a problem encountered several years ago. This project, using galvanized reinforcement, began over twenty years ago. Since that time, epoxy coated reinforcement has become the specified material used in bridge decks.</p> <p>The decks researched in this project are located on I-35 in Story County. They were constructed in 1967.</p> <p>The results from the testing done on this project show that galvanizing protects steel from corrosion due to deicing salts, resulting in less/no concrete deterioration.</p> | |
| 9. KEY WORDS | 10. NO. OF PAGES |
| Galvanized reinforcement, Bridges, Corrosion, Reinforcing steel | 59 |

TABLE OF CONTENTS

| | Page |
|--|------|
| Introduction..... | 1 |
| Objective..... | 1 |
| Project Description..... | 1 |
| Materials..... | 2 |
| Construction..... | 3 |
| Testing..... | 3 |
| Discussion of Results..... | 4 |
| Summary..... | 4 |
| Conclusions..... | 4 |
| Acknowledgement..... | 5 |
| Appendices | |
| Appendix A - Steel Placement and Concrete Placement Test Results..... | 6 |
| Appendix B - Annual Test Results..... | 16 |
| Appendix C - Construction Technology Laboratory.... Results | 25 |

DISCLAIMER

The contents of this report reflect the views of the author and do not necessarily reflect the official views of the Iowa Department of Transportation. This report does not constitute any standard, specification or regulation.

INTRODUCTION

The corrosion of untreated reinforcing steel in bridge decks prompted this research over twenty years ago. At that time, untreated black steel was the primary reinforcement used. The corrosion of the untreated steel caused deterioration of the bridge decks. This was due to deicing salts penetrating the surface of the deck to the underlying steel. The steel would then corrode resulting in cracking and spalling of the concrete surrounding the steel in the bridge deck.

In this project galvanized reinforcement was used in part of the deck and compared to the conventional uncoated steel.

There were also some researchers who suggested that there would be adverse chemical reactions between the concrete and the galvanizing.

OBJECTIVE

The objective of this project was to determine the durability of a bridge deck constructed using galvanized reinforcing steel.

PROJECT DESCRIPTION

This project is located on I-35 over Long Dick Creek in Story County. There are two structures, one northbound and one southbound. The bridges are dual 193'-0 x 39' pretensioned prestressed concrete bridges with three spans of 64'-1", 64'-10" and 64'-1".

Each deck incorporated both untreated and galvanized steel. The deck of the southbound lane contained both transverse and longitudinal rebar of galvanized steel. The galvanized rebar are located only in the south half of the bridge and only the top layer of steel is galvanized. Galvanized tie wires were used in this section. The deck of the northbound bridge contains galvanized rebar for transverse steel only. These galvanized rebars were placed in the south half of the deck and were placed as the top layer of reinforcing steel. The north half of the deck used all untreated rebar. Uncoated tie wires were used in this deck. The figures in Appendix A show the placement of steel in both bridges. The depth of cover of the concrete over the galvanized steel reinforcement ranged from 2 1/2" to 5" with an average of 3" depth.

MATERIALS

In these bridge decks, No. 5, 6 and 7 bars were used. The coating thickness was checked on the galvanized bars before construction. The results are in Table I.

TABLE I

| Bar Size No. | Spelter oz./ft. ² |
|-----------------|---------------------------------|
| 5 | 4.7 |
| 6 | 5.4 |
| 7 | 2.8 |

The galvanized coating thickness exceeds 1.2 oz./ft.² required by ASTM A-123.

The concrete mix design consisted of a cement factor of 710 lbs./cu.yd. and a water cement ratio of .40 to .41. The entrained air content ranged from 5.2% to 6.2%. NCHRP Report 23 noted that the concrete placement must be carefully supervised since it did represent a potentially large variable. A pictorial diagram of the location of each truck load of concrete was kept to show where it was placed and the slump and air in each location. This diagram is in Appendix A.

CONSTRUCTION

All regular construction field procedures were followed. More loads were tested so the construction of the deck could be documented. Rain occurred during the placement on the south span of the northbound bridge. This was documented in case scaling would eventually occur. No scaling, however, did occur in this section.

TESTING

The Iowa DOT performed electrical potential testing, obtained cores for chloride determination and checked for delaminations every other year. Those results are shown in Appendix B. Construction Technology Laboratories (CTL) completed testing in 1975, 1982 and 1991. They measured electrical potentials and water soluble chloride ion contents of concrete at the depth of embedded steel reinforcement. They also inspected the concrete deterioration, did petrographic examination to determine concrete quality, and metallographic analysis of galvanized coating. These results are in Appendix C.

DISCUSSION OF RESULTS

The results of the tests performed on these bridge decks showed that galvanized reinforcement showed little evidence of corrosion. There was no direct correlation of concrete deterioration related to corrosion of embedded steel reinforcement. It is also possible that any corrosion that did occur could have occurred before or immediately after placement of concrete.

SUMMARY

Based on some researchers' findings in the past, it is believed that galvanized steel develops sacrificial expansion products resulting in concrete deterioration. This has not proven true in this instance. Recent research has not uncovered any significant long term problems with galvanized reinforcement. Galvanized steel was at a disadvantage at first because both mats had to be galvanized, while with epoxy, only the top layer of steel was required to be coated. Approximately 4 years ago epoxy coated steel was also required on both layers because of transverse cracking which allows deicing salt brine to reach the bottom layer. From this and other studies that have been completed, it appears galvanized reinforcement has proven to be an effective method of preventing corrosion in bridge decks.

CONCLUSIONS



1. Galvanized reinforcement on this bridge provided satisfactory resistance to corrosion with a 2 1/2" or greater cover.

2. The galvanized reinforcement caused no problems on this bridge deck.


ACKNOWLEDGEMENT

The author wishes to express appreciation to Brian G. Stejskal of Construction Technology Laboratories and Dick Smith who has retired from the Iowa DOT for developing material used in this report.

Appendix A
Steel Placement and Concrete Placement Test Results





Sketch of typical section
near abutment




Sketch of typical section
near pier

Deck - Southbound Lane
figure 2




Sketch of typical section
near abutment



Sketch of typical section
near pier


Deck - Northbound Lane

figure 3




Layout of Bridge Deck Sections


Figure 4




Section 1 - Slump & Air Content



South Bound Lane




Section 3 - Slump & Air Content




Section 4 - Slump & Air Content

North Pier



Section 5 Slump and Air Content



Appendix B
Annual Test Results

Iowa DOT Project HR-504

IA-66-01

Galvanized Bridge Deck Reinforcing

I-35 Northbound over Long Dick Creek
Delamination - Nil
Curbs badly deteriorated


I-35 Southbound over Long Dick Creek
2 sq. ft. Delaminated in shoulder area
5 sq. ft. Spalled in shoulder area

I-35 over Long Dick Creek
Story County

193' x 39' Dual Prestressed Concrete Beam Bridge
Constructed 1967

November 1977-All corrosion readings were less than 0.30 volt

 - Test Section Locations



Bridge: I-35 over Long Dick Creek - Story County

CHLORIDE CONTENT - LBS/CU. YD.

| Year Sampled | Sample Depth (Inches) | | | | |
|-----------------|-----------------------|-------|-----------|---|------------|
| | 0 - 0.75 | 0 - 1 | 0.75- 1.5 | | 1.5 - 2.25 |
| 1973 | | | | | |
| S bound | | 3.86 | - | - | 1.78 |
| | | 5.10 | - | - | 3.40 |
| N bound | | 3.78 | - | - | 3.21 |
| | | 3.40 | - | - | 1.40 |
| 1974 | | | | | |
| S bound | | 2.46 | - | - | 0.96 |
| | | 3.64 | - | - | 0.83 |
| N bound | | 2.03 | - | - | 0.94 |
| | | 1.30 | - | - | 0.88 |
| 1975 | | | | | |
| S bound | | 2.1 | - | - | 0.5 |
| | | 2.3 | - | - | 0.5 |
| N bound | | 3.1 | - | - | 0.7 |
| | | 2.4 | - | - | 0.6 |
| 1976 | | | | | |
| S bound | | 5.2 | - | - | 0.5 |
| | | 4.8 | - | - | 0.6 |
| N bound | | 1.8 | - | - | 0.4 |
| | | 8.3 | - | - | 0.5 |
| 1977 | | | | | |
| S bound | 7.45 | - | 0.48 | - | 0.33 |
| | 9.22 | - | 1.01 | - | 0.55 |
| | 9.53 | - | 2.15 | - | 0.52 |
| | 11.34 | - | 1.78 | - | 3.03 |
| N bound | 16.75 | - | 4.69 | - | 1.03 |
| | 5.18 | - | 1.03 | - | 0.70 |
| | 7.79 | - | 1.35 | - | 0.55 |
| 1979 | | | | | |
| S bound | 8.01 | - | 0.45 | - | 0.42 |
| | 11.00 | - | 0.87 | - | 0.45 |
| N bound | 8.28 | - | 1.97 | - | 0.42 |
| | 4.20 | - | 1.97 | - | 0.64 |

Bridge: I-35 over Long Dick Creek - Story County


CHLORIDE CONTENT - LBS/CU. YD.

| Year Sampled | Sample Depth (Inches) | | | | |
|-----------------|-----------------------|-------|----------|---|------------|
| | 0 - 0.75 | 0 - 1 | 0.75-1.5 | | 1.5 - 2.25 |
| 1981 | | | | | |
| S bound | 13.19 | - | 8.35 | - | 0.56 |
| | 10.28 | - | 3.63 | - | 0.68 |
| N bound | 5.93 | - | 0.30 | - | 0.49 |
| | 5.07 | - | 0.95 | - | 0.30 |

Bridge: I-35 Northbound over Long Dick Creek

CHLORIDE CONTENT - LBS/CU. YD.

| Year Sampled | Sample Depth (Inches) | | | | |
|-----------------|-----------------------|---------|---------|---------|---------|
| | 0 - 0.5 | 0.5 - 1 | 1 - 1.5 | 1.5 - 2 | 2 - 2.5 |
| 1983 | 11.87 | 4.95 | 1.13 | 0.34 | 0.42 |
| | 14.44 | 4.23 | 0.60 | 0.57 | 0.49 |
| | 9.68 | 2.95 | 1.40 | 0.53 | 0.38 |
| | 6.13 | 1.66 | 0.45 | 0.26 | 0.19 |
| | 7.11 | 1.06 | 0.38 | 0.30 | 0.53 |
| | 5.56 | 1.44 | 0.53 | 0.42 | 0.53 |
| | 5.86 | 0.15 | 0.30 | 0.30 | 0.30 |
| | | | | | |
| 1985 | 9.03 | 3.89 | 1.32 | 0.76 | 0.49 |
| | 10.09 | 0.64 | 2.19 | 0.71 | 0.49 |
| | 11.26 | 5.10 | 1.32 | 0.30 | 0.38 |
| | 11.23 | 3.33 | 0.91 | 1.78 | 0.76 |
| | 3.21 | 1.17 | 0.79 | 0.42 | 0.68 |
| | 4.23 | 1.06 | 0.72 | 0.68 | 0.45 |
| 1987 | 8.20 | 5.52 | 1.40 | 0.53 | 0.53 |
| | 4.91 | 1.66 | 0.87 | 0.64 | 0.45 |
| | 10.51 | 4.57 | 3.67 | 1.13 | 0.87 |
| | 5.03 | 2.15 | 1.74 | 1.51 | 1.51 |
| | 5.82 | 1.70 | 0.83 | 0.45 | 0.45 |
| | 4.61 | 0.49 | 0.57 | 0.45 | 0.57 |
| | 6.50 | 0.95 | 0.57 | 0.57 | ----- |
| | | | | | |
| 1989 | 13.08 | 6.16 | 3.67 | 1.40 | 0.76 |
| | 6.54 | 2.65 | 1.25 | 1.13 | 0.76 |
| | 15.76 | 11.72 | 8.69 | 4.80 | 0.38 |
| | 8.69 | 1.63 | 0.87 | 0.87 | 0.87 |
| | 10.47 | 2.65 | 1.51 | 0.87 | 0.76 |
| | 10.96 | 3.40 | 1.13 | 0.64 | 0.76 |




Electrical Potential (x .01 v)
 I-35 Northbound over Long Dick Creek - Story County
 Galvanized Steel in Part of Deck
 Constructed in 1967

Bridge: I-35 Southbound over Long Dick Creek - Story County


CHLORIDE CONTENT - LBS/CU. YD.

| Year Sampled | Sample Depth (Inches) | | | | |
|-----------------|-----------------------|---------|---------|---------|---------|
| | 0 - 0.5 | 0.5 - 1 | 1 - 1.5 | 1.5 - 2 | 2 - 2.5 |
| 1983 | 13.23 | 6.54 | 1.51 | 0.45 | 0.76 |
| | 7.64 | 1.59 | 0.30 | 0.45 | 0.64 |
| | 14.33 | 11.60 | 2.61 | 0.26 | 0.26 |
| | 12.13 | 0.76 | 0.26 | 0.45 | 0.45 |
| | 13.95 | 3.36 | 0.60 | 0.23 | 0.30 |
| | 12.55 | 3.67 | 1.29 | 0.38 | 0.60 |
| 1985 | 8.51 | 2.76 | 0.68 | 0.57 | 0.53 |
| | 13.65 | 1.44 | 0.83 | 1.06 | 0.46 |
| | 7.52 | 2.72 | 0.83 | 0.64 | 0.60 |
| | 14.18 | 7.98 | 7.98 | 0.57 | ---- |
| | 26.99 | 14.82 | 9.19 | 2.72 | 0.64 |
| | 11.68 | 0.64 | 0.57 | 0.57 | 0.30 |
| 1987 | 10.09 | 3.97 | 1.02 | 0.49 | 0.68 |
| | 6.12 | 1.51 | 0.64 | 0.76 | 0.38 |
| | 10.77 | 0.91 | 0.23 | 0.83 | 0.49 |
| | 4.23 | 0.64 | 0.45 | 0.45 | 0.57 |
| | 15.08 | 3.78 | 0.45 | 0.30 | 0.87 |
| | 9.60 | 5.67 | 0.95 | 0.38 | 0.30 |
| | 11.64 | 1.44 | 0.83 | 0.38 | 0.45 |
| | 12.74 | 1.70 | 0.49 | 0.53 | 0.64 |



Appendix C
Construction Technology Laboratory Results

Section A.2: IOWA STRUCTURE



AMES BRIDGE:

Identification:

Two bridges on I-35 over Long Dick Creek (Story County) located near Ames, Iowa. The dual concrete decks service northbound and southbound traffic and are supported by two piers.

Year of Construction: 1967

Age: 24 years

Description:

The subject structure is a dual 3-span bridge which was previously inspected in 1981. All three spans of both decks were included for study. The bridge decks measure approximately 193 x 39 ft each and are composed of prestressed concrete beams spanning 64 to 65 ft. Reinforced concrete decks are constructed with both treated and galvanized steel reinforcing bars, as indicated on the next page.

Detail of Steel Reinforcement:

The north halves of both decks are constructed with untreated steel reinforcement in the longitudinal and transverse direction. The top mat in the south half of the concrete deck servicing southbound traffic contains galvanized longitudinal and transverse steel bars. Galvanized steel reinforcement is secured with galvanized steel wires. The top mat in the south half of the northbound deck contains galvanized transverse steel, and untreated longitudinal steel bars. Standard uncoated tie wires were used in this section of the bridge deck. The bottom steel reinforcing mats in both northbound and southbound decks are constructed with untreated steel bars.

Concrete Mix Design:

| | |
|------------------------|-----------------------------------|
| Cement Factor: | 710 lbs/cu yd (7.55 bags/cu yd). |
| Water-to-Cement Ratio: | 0.40 to 0.41 (4.5 to 4.6 gal/bag) |
| Air Content: | 5.2 to 6.2% |

Electrical Potentials:

Electrical potential survey results are presented in Figs. A.2.(a - f). Areas of similar potential are defined by equipotential lines at 100 millivolt intervals. Electrical potential measurements were recorded on a 5 ft. grid pattern.

Surface Defects:

Concrete deterioration in the form of cracking was observed on exposed deck surfaces. Concrete cracking oriented in the transverse direction is shown in Figs. A.2.(g - i). In some instances, cracks occur over embedded steel reinforcement.

Subsurface Delaminations:

Sounding of concrete decks indicated minor subsurface delaminations and small unbonded surfaces at isolated areas.

Chloride Analysis:

Water-soluble chloride content analysis of 12 concrete powder samples removed from the subject decks was performed. Tests were conducted in accordance with ASTM C 144 and analysis performed by potentiometric titration with silver nitrate. Results of tests are summarized in Table A.2.

Petrographic Examination:

Eight concrete core samples were removed from the concrete decks at locations designated as L-1, L-2, L-4, L-6, L-10, L-11, L-13, and L-14. The location and description of core samples taken for study are presented in Table A.2. Petrographic examinations were performed on three of the cores (L-6, L-10, and L-14) to evaluate the condition and quality of concrete in respective deck slabs. Petrographic examinations were performed on the core samples in accordance with ASTM Designation C 856-83. Results of the examinations indicated the following:

| Core Designation | Depth of Carbonation (inch) | Estimated Water/Cement Ratio | Air-Entrainment | Air Content |
|------------------|-----------------------------|------------------------------|-----------------|-------------|
| L-6 | 0.10 | 0.50 to 0.55 | Air-Entrained | 4 to 6% |
| L-10 | 0.10 | 0.45 to 0.50 | Air-Entrained | 3 to 5% |
| L-14 | 0.10 | 0.50 to 0.55 | Air-Entrained | 4 to 6% |

Cores L-10 and L-14 exhibited vertical cracks and corrosion on steel reinforcement (reference Table A.2). In addition, microcracking was observed around chert and dolomitic chert, which are reactive fine aggregates that can cause internal concrete deterioration.

Metallographic Measurements:

Core L-6: Core sample contained a single reinforcing bar (No. 6) with a galvanized coating which averaged 3.8 mils thick. The coating structure consists of a blocky delta layer and a columnar growth of zeta crystals which are covered with a layer of pure zinc (eta layer). The smooth surface of the coating suggests that the sample has experienced only minimal corrosion attack.

Core L-10: Core sample shows a direct comparison between a coated bar (No. 5) and an uncoated steel bar (No. 6). The slightly ragged surface profile of the galvanized coating indicated that slight attack has taken place, although the coating still averages approximately 4.7 mils thick. The uncoated bar, which has a greater depth of concrete cover than the galvanized bar exhibits red rusting over almost half of its length.

Core L-14: Core sample contained two uncoated reinforcing bars (No. 5 and No. 6). Both of the bars appeared to be in good condition.

The following is a summary of the metallographic examination:

| Core Designation | Bar Size | Depth of Concrete Cover (inches) | Galvanized Coating Thickness (mils) |
|------------------|----------|----------------------------------|-------------------------------------|
| L-6 | No. 6 | 3 | 3.8 |
| L-10 | No. 5 | 3-1/4 | 4.7 |
| | No. 6 | 4-7/8 | (Uncoated) |
| L-14 | No. 5 | 2-1/2 | (Uncoated) |
| | No. 6 | 3-1/4 | (Uncoated) |

Table A.2: CONCRETE CORE AND POWDER SAMPLE SUMMARY

AMES BRIDGE, IOWA

CONCRETE CORE DESCRIPTIONS:

| CTL CORE DESIGNATION | LOCATION | STEEL REINFORCEMENT | DEPTH OF CONC. COVER (Inches) | COMMENTS |
|-------------------------|-----------------------------|------------------------|----------------------------------|--|
| L-6 | SOUTH SPAN (N.B. Lanes) | No. 6 Bar No. 7 Bar | 3" 3-7/8" | No Corrosion Detected (Same) |
| L-10 | SOUTH SPAN (S.B. Lanes) | No. 6 Bar No. 7 Bar | 3-1/4" 4-7/8" | No Corrosion Detected Crack, Corrosion Detected |
| L-13 | MIDDLE SPAN (S.B. Lanes) | No. 7 Bar No. 5 Bar | 2-5/8" 3-1/4" | Crack, No Corrosion No Corrosion Detected |
| L-14 | NORTH SPAN (S.B. Lanes) | No. 6 Bar No. 6 Bar | 2-1/2" 3-1/4" | Light Corrosion Detected (Same) |

CHLORIDE ION TEST RESULTS:

| CTL Powder Designation | SPAN (Lanes) | Depth of Powder Sample (Inches) | Electro-Potential Readings (MV) | Water-Soluble Chloride Content |
|---------------------------|-----------------|------------------------------------|------------------------------------|-----------------------------------|
| L1A | MIDDLE (N.B.) | 2-1/4 to 2-3/4 | 170 | 0.257 |
| L2 | NORTH (N.B.) | 2-1/4 to 2-3/4 | 135 | 0.057 |
| L3A | NORTH (N.B.) | 2-1/2 to 3 | 60 | 0.043 |
| L4A | SOUTH (N.B.) | 2-1/4 to 2-3/4 | 135 | 0.086 |
| L5A | SOUTH (N.B.) | 2-1/4 to 2-3/4 | 135 | 0.036 |
| L6A | SOUTH (N.B.) | 2-1/4 to 2-3/4 | 370 | 0.171 |
| L7A | SOUTH (S.B.) | 2-1/4 to 2-3/4 | 370 | 0.186 |
| L8A | NORTH (S.B.) | 2-1/4 to 2-3/4 | 360 | 0.343 |
| L9A | SOUTH (S.B.) | 2-1/4 to 2-3/4 | 300 | 0.193 |
| L11 | SOUTH (S.B.) | 2-1/2 to 3 | 70 | 0.057 |
| L12 | SOUTH (S.B.) | 1-1/2 to 2-1/4 | 120 | 0.714 |
| L13 | MIDDLE (S.B.) | 2-1/4 to 2-3/4 | 60 | 0.121 |

* Based on an estimated cement content of 14%
(by weight of cement)







FIG A.2(a)


CTL 050324

AMES BRIDGE
(I-35 over Long Dick Creek)

Iowa Department of Transportation
AMES, IOWA (Story County)
DISTRICT 3



(NORTH END OF BRIDGE)



(SOUTH END OF SPAN)

MIDDLE SPAN

Iowa Department of Transportation
AMES, IOWA (Story County)
DISTRICT 3

AMES BRIDGE
(I-35 over Long Dick Creek)

FIG A.2(b)
CTL 050324








FIG A.2(c)

AMES BRIDGE
(I-35 over Long Dick Creek)

Iowa Department of Transportation
AMES, IOWA (Story County)
DISTRICT 3

CTL 050324

Construction Technology Laboratories, Inc.



(NORTH END OF BRIDGE)


| | | | | | | | | | | | | |
|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 181 | 153 | 198 | 80 | 48 | 70 | 94 | 157 | 107 | 193 | 175 | 184 | 225 |
| 262 | 204 | 123 | 105 | 93 | 194 | 146 | 149 | 128 | 123 | 133 | 284 | 180 |
| 284 | 207 | 119 | 108 | 83 | 147 | 123 | 125 | 115 | 184 | 128 | 108 | 161 |
| 253 | 100 | 144 | 103 | 137 | 156 | 129 | 123 | 125 | 151 | 121 | 165 | 137 |
| 261 | 137 | 114 | 78 | 77 | 103 | 99 | 76 | 114 | 112 | 69 | 140 | 112 |
| 184 | 150 | 119 | 97 | 126 | 114 | 98 | 127 | 125 | 109 | 119 | 108 | 138 |
| 212 | 173 | 155 | 142 | 94 | 96 | 120 | 111 | 125 | 130 | 112 | 94 | 154 |
| 217 | 184 | 133 | 124 | 136 | 113 | 157 | 108 | 105 | 85 | 75 | 77 | 188 |
| 313 | 167 | 94 | 59 | 27 | 30 | 72 | 91 | 80 | 58 | 43 | 249 | 88 |
| 384 | 101 | 110 | 85 | 38 | 84 | 45 | 105 | 87 | 59 | 75 | 110 | 75 |
| 323 | 85 | 100 | 102 | 72 | 78 | 100 | 170 | 46 | 21 | 43 | 363 | 172 |
| 288 | 80 | 71 | 48 | 41 | 52 | 80 | 83 | 87 | 21 | 80 | 128 | 17 |
| 300 | 113 | 83 | 72 | 46 | 100 | 84 | 116 | 87 | 82 | 97 | 140 | 87 |
| 177 | 50 | 20 | 20 | 1 | 35 | 84 | 132 | 40 | 46 | 90 | 165 | 28 |
| 218 | 100 | 7 | 3 | 15 | 45 | 42 | 15 | 12 | 30 | 66 | 98 | 70 |
| 150 | 40 | 10 | 10 | 13 | 11 | 12 | 17 | 2 | 35 | 34 | 110 | 115 |

NORTH SPAN

(SOUTH END OF SPAN)

Northbound
Lanes

Southbound
Lanes



(NORTH END OF BRIDGE)


| | | | | | | | | | | | | |
|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 286 | 333 | 260 | 186 | 258 | 80 | 133 | 251 | 164 | 248 | 227 | 179 | 284 |
| 215 | 236 | 247 | 273 | 215 | 74 | 136 | 103 | 85 | 173 | 193 | 166 | 280 |
| 209 | 236 | 203 | 212 | 70 | 94 | 71 | 80 | 122 | 121 | 118 | 117 | 371 |
| 143 | 186 | 140 | 140 | 204 | 135 | 47 | 71 | 87 | 133 | 115 | 136 | 314 |
| 129 | 173 | 161 | 174 | 158 | 102 | 92 | 85 | 61 | 109 | 151 | 151 | 382 |
| 208 | 141 | 282 | 167 | 132 | 103 | 165 | 94 | 91 | 138 | 97 | 138 | 180 |
| 182 | 150 | 202 | 85 | 143 | 99 | 112 | 52 | 132 | 81 | 114 | 112 | 220 |
| 138 | 238 | 328 | 67 | 268 | 168 | 114 | 58 | 130 | 86 | 68 | 169 | 208 |
| 135 | 93 | 149 | 148 | 52 | 100 | 210 | 80 | 130 | 91 | 285 | 351 | 745 |
| 143 | 180 | 125 | 88 | 52 | 38 | 145 | 82 | 127 | 70 | 82 | 173 | 284 |
| 268 | 388 | 182 | 152 | 47 | 110 | 162 | 47 | 192 | 82 | 89 | 88 | 318 |
| 117 | 152 | 104 | 68 | 72 | 75 | 31 | 83 | 140 | 34 | 72 | 82 | 292 |
| 98 | 129 | 76 | 53 | 96 | 50 | 75 | 111 | 67 | 49 | 69 | 121 | 229 |
| 139 | 248 | 57 | 21 | 80 | 50 | 29 | 36 | 14 | 3 | 83 | 105 | 235 |
| 80 | 112 | 80 | 97 | 34 | 31 | 52 | 40 | 173 | 20 | 71 | 46 | 278 |
| 26 | 25 | 33 | 21 | 18 | 40 | 41 | 1 | 3 | 2 | 31 | 85 | 33 |

Northbound
Lanes


Southbound
Lanes

(SOUTH END OF SPAN)

SOUTH SPAN



(NORTH END OF BRIDGE)





CRACKING IN
CONCRETE

MIDDLE SPAN

(SOUTH END OF SPAN)

Northbound
Lanes

Southbound
Lanes



(NORTH END OF BRIDGE)



| | | | | | | | | | | | | |
|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 181 | 153 | 198 | 80 | 48 | 70 | 84 | 137 | 107 | 199 | 175 | 184 | 225 |
| 242 | 204 | 123 | 105 | 93 | 194 | 146 | 140 | 128 | 123 | 133 | 284 | 180 |
| 284 | 207 | 119 | 108 | 83 | 147 | 123 | 125 | 115 | 184 | 128 | 108 | 161 |
| 253 | 100 | 144 | 103 | 137 | 156 | 129 | 123 | 125 | 151 | 121 | 165 | 137 |
| 281 | 137 | 114 | 78 | 77 | 103 | 99 | 76 | 114 | 112 | 69 | 140 | 112 |
| 184 | 150 | 119 | 97 | 126 | 114 | 98 | 127 | 125 | 109 | 119 | 108 | 138 |
| 212 | 173 | 155 | 142 | 94 | 96 | 120 | 111 | 125 | 130 | 112 | 94 | 154 |
| 217 | 184 | 133 | 124 | 136 | 113 | 157 | 106 | 105 | 85 | 75 | 77 | 186 |
| 313 | 167 | 94 | 59 | 27 | 30 | 72 | 81 | 80 | 58 | 43 | 249 | 88 |
| 384 | 101 | 110 | 85 | 38 | 84 | 45 | 105 | 87 | 59 | 75 | 110 | 75 |
| 323 | 85 | 100 | 102 | 72 | 78 | 100 | 120 | 48 | 21 | 43 | 383 | 172 |
| 288 | 80 | 71 | 46 | 41 | 52 | 80 | 83 | 87 | 21 | 80 | 129 | 17 |
| 300 | 113 | 83 | 72 | 46 | 100 | 84 | 116 | 87 | 82 | 97 | 140 | 87 |
| 177 | 50 | 20 | 20 | 1 | 35 | 84 | 132 | 40 | 48 | 90 | 165 | 28 |
| 218 | 100 | 7 | 3 | 15 | 45 | 42 | 15 | 12 | 30 | 86 | 98 | 70 |
| 150 | 40 | 10 | 10 | 13 | 11 | 12 | 17 | 2 | 35 | 34 | 110 | 115 |

Northbound
Lanes

Southbound
Lanes

(SOUTH END OF SPAN)

NORTH SPAN



(NORTH END OF BRIDGE)

| | | | | | | | | | | | | |
|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 100 | 123 | 143 | 216 | 213 | 228 | 206 | 160 | 228 | 185 | 303 | 282 | 208 |
| 152 | 201 | 147 | 147 | 154 | 392 | 164 | 130 | 172 | 164 | 380 | 340 | 172 |
| 146 | 124 | 138 | 140 | 122 | 131 | 130 | 142 | 146 | 140 | 158 | 227 | 191 |
| 192 | 136 | 173 | 160 | 146 | 151 | 142 | 128 | 76 | 96 | 100 | 123 | 102 |
| 190 | 190 | 155 | 198 | 198 | 132 | 124 | 94 | 82 | 234 | 131 | 104 | 116 |
| 389 | 238 | 152 | 169 | 217 | 135 | 157 | 313 | 155 | 137 | 181 | 287 | 144 |
| 310 | 186 | 185 | 131 | 186 | 152 | 144 | 183 | 141 | 146 | 154 | 188 | 183 |
| 264 | 357 | 45 | 184 | 109 | 84 | 101 | 158 | 181 | 183 | 208 | 281 | 218 |
| 47 | 276 | 138 | 77 | 28 | 96 | 97 | 69 | 45 | 121 | 268 | 105 | 144 |
| 128 | 151 | 105 | 83 | 93 | 68 | 112 | 82 | 35 | 103 | 118 | 111 | 188 |
| 93 | 183 | 150 | 59 | 64 | 64 | 184 | 107 | 78 | 118 | 182 | 117 | 158 |
| 146 | 87 | 56 | 91 | 35 | 36 | 58 | 79 | 82 | 81 | 78 | 108 | 100 |
| 144 | 88 | 48 | 60 | 75 | 26 | 30 | 87 | 65 | 64 | 72 | 98 | 83 |
| 146 | 40 | 14 | 44 | 27 | 8 | 88 | 30 | 42 | 66 | 50 | 17 | 43 |
| 23 | 2 | 84 | 54 | 44 | 0 | 106 | 14 | 71 | 84 | 191 | 21 | 40 |
| 29 | 10 | 23 | 24 | 20 | 20 | 55 | 47 | 27 | 17 | 128 | 2 | 5 |

MIDDLE SPAN

(SOUTH END OF SPAN)

Northbound Lanes



Southbound Lanes

Iowa Department of Transportation
AMES, IOWA (Story County)
DISTRICT 3

AMES BRIDGE
(I-35 over Long Dick Creek)

FIG A.2(c)

CTL 050324



(NORTH END OF BRIDGE)


| | | | | | | | | | | | | |
|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| 286 | 333 | 260 | 186 | 258 | 80 | 133 | 251 | 164 | 248 | 227 | 179 | 284 |
| 215 | 236 | 247 | 273 | 215 | 74 | 136 | 103 | 85 | 173 | 193 | 166 | 280 |
| 209 | 236 | 203 | 212 | 70 | 94 | 71 | 80 | 122 | 121 | 118 | 117 | 371 |
| 143 | 186 | 140 | 140 | 204 | 135 | 47 | 71 | 87 | 133 | 115 | 136 | 314 |
| 129 | 173 | 161 | 174 | 158 | 102 | 92 | 85 | 61 | 109 | 151 | 151 | 382 |
| 208 | 141 | 282 | 167 | 132 | 103 | 165 | 94 | 91 | 138 | 97 | 138 | 180 |
| 182 | 150 | 202 | 85 | 143 | 99 | 112 | 52 | 132 | 81 | 114 | 112 | 220 |
| 138 | 238 | 328 | 67 | 268 | 168 | 114 | 58 | 130 | 86 | 68 | 169 | 208 |
| 135 | 93 | 149 | 148 | 52 | 100 | 210 | 80 | 130 | 91 | 285 | 351 | 745 |
| 143 | 180 | 125 | 88 | 52 | 38 | 145 | 82 | 127 | 70 | 82 | 173 | 284 |
| 268 | 388 | 182 | 152 | 47 | 110 | 162 | 47 | 192 | 82 | 89 | 88 | 318 |
| 117 | 152 | 104 | 68 | 72 | 75 | 31 | 83 | 140 | 34 | 72 | 82 | 292 |
| 98 | 129 | 76 | 53 | 96 | 50 | 75 | 111 | 67 | 49 | 69 | 121 | 228 |
| 139 | 248 | 57 | 21 | 80 | 50 | 29 | 36 | 14 | 3 | 83 | 105 | 235 |
| 80 | 112 | 80 | 97 | 34 | 31 | 52 | 40 | 173 | 20 | 71 | 46 | 278 |
| 26 | 25 | 33 | 21 | 18 | 40 | 41 | 1 | 3 | 2 | 31 | 85 | 33 |

Northbound
Lanes


Southbound
Lanes

(SOUTH END OF SPAN)

SOUTH SPAN



(NORTH END OF BRIDGE)



CRACKING IN
CONCRETE

NORTH SPAN

(SOUTH END OF SPAN)

Northbound
Lanes


Southbound
Lanes

SMALL
DELAMINATION


Iowa Department of Transportation
AMES, IOWA (Story County)
DISTRICT 3

AMES BRIDGE
(I-35 over Long Dick Creek)

FIG A.2(g)
CTL 050324




(NORTH END OF BRIDGE)



CRACKING IN
CONCRETE

(SOUTH END OF SPAN)



MIDDLE SPAN





Iowa Department of Transportation
AMES, IOWA (Story County)
DISTRICT 3

AMES BRIDGE
(I-35 over Long Dick Creek)

FIG A.2(i)
CTL 050324

AMES BRIDGEPHOTOS A.2(a & b):

Representative Conditions of Bridge Deck Wearing Surface (Note areas of concrete deterioration and asphalt patch shown in Photo b)

AMES BRIDGEPHOTOS A.2(c & d):

Close-up Views of Core Sample L-1 Note that the water-soluble chloride ion content in powder sample L-1A was 0.257 (by weight of cement), at a depth of approximately 2-1/2-in. Potential survey results indicated a reading of -170 mv in adjacent concrete.


AMES BRIDGE

PHOTO A.2(e):

Steel samples removed from Core Sample L-6.






PHOTO A.2(f):


Magnification of No. 6 Bar removed from Core Sample L-6 (galvanized coating thickness of 3.8 mils).

AMES BRIDGEPHOTO A.2(g):

Steel samples removed from Core Sample L-10.

PHOTO A.2(h):

Magnification of No. 5 Bar removed from Core Sample L-10 (galvanized coating thickness of 4.7 mils).

AMES BRIDGEPHOTO A.2(i):

Steel samples removed from Core Sample L-14.

PHOTO A.2(j):

Magnification of No. 6 Bar removed from Core Sample L-14 (steel reinforcement is uncoated).

PETROGRAPHIC EXAMINATION OF HARDENED CONCRETE, ASTM C 856

CTL PROJECT NO.: 154070

CLIENT: International Lead Zinc Research Organization

STRUCTURE: Bridge Deck

LOCATION: Ames, Iowa

DATE: January 22, 1992

PROBLEM: Quality Evaluation

EXAMINED BY: L. Powers-Couche

Page 6 of 25

SAMPLE:

Identification: L6.

Dimensions: Diameter = 4.0 in.; Length = 4.0 to 5.0 in.

Top Surface: Abraded surface with exposed coarse aggregate. Aggregate particles are polished and stand out in relief against softer paste.

Bottom Surface: Broken surface fractured around aggregate.

Cracks, Joints, Large Voids: Many areas of underconsolidation. The largest underconsolidated area is 1.5 in. long and 2.0 in. wide.

Reinforcement: No. 6 rebar is located 3.0 in from top surface.

AGGREGATES (A)

Coarse (C): Siliceous and calcareous gravel consisting of granite, limestone, chert, altered volcanic rock (hematitic and silicified), and schist.

Fine (F): Siliceous and calcareous sand consisting of quartzite, quartz, limestone, chert, feldspar, schist, hornblende, granite, graywacke, and hematite-cemented sandstone.

Gradation & Top Size: Evenly graded to a top size of 0.7 in.

Shape & Distribution: CA is rounded to subangular, equidimensional to elongate, and somewhat nonuniformly distributed. FA is rounded to subangular, equidimensional, and uniformly distributed.

PASTE

Color: Medium gray.

Hardness: Moderately hard.

Luster: Subvitreous.

Calcium Hydroxide*: 7 to 10% uniformly distributed small crystals.

Unhydrated Portland Cement Clinker Particles (UPC's)*: 8 to 12% uniformly distributed UPC's and relics.

Depth of Carbonation: 0.1 in. from top surface.

Air Content: 4 to 6% uniformly distributed, small, spherical air voids and irregularly shaped, larger (up to 0.5 in.) paste-lined, entrapped air voids.

Fly Ash*: None observed.

Paste-Aggregate Bond: Moderately tight. The concrete breaks around the smooth, hard coarse aggregates.

Secondary Deposits: Inwardly-pointing ettringite needles line or fill voids.

*percent by volume of paste

Microcracking: No significant microcracks are observed.

ESTIMATED WATER-CEMENT RATIO: 0.50 to 0.55.

MISCELLANEOUS: Chert particles have dark rims, however, no other evidence of alkali-silica reaction is observed. The paste is carbonated around limestone particles and around some larger air voids.

PETROGRAPHIC EXAMINATION OF HARDENED CONCRETE, ASTM C 856

CTL PROJECT NO.: 154070

CLIENT: International Lead Zinc Research Organization

STRUCTURE: Bridge Deck

LOCATION: Ames, Iowa

DATE: January 22, 1992

PROBLEM: Quality Evaluation

EXAMINED BY: L. Powers-Couche

Page 8 of 25

SAMPLE:

Identification: L10.

Dimensions: Diameter = 4.0 in.; Length = 6.5 in.

Top Surface: Abraded surface with coarse aggregates exposed. Aggregates are polished and stand out in relief against softer paste.

Bottom Surface: Irregular, broken surface fractured through aggregates.

Cracks, Joints, Large Voids: The concrete is generally well consolidated with no visible joints and few voids larger than 0.2 in. Two major vertical cracks which mostly pass around aggregates pass lengthwise through the core.

Reinforcement: No. 5 rebar is located 3.2 in. from the top surface. No 6 rebar is 5.0 in. from the top and is corroded.

AGGREGATES (A)

Coarse (C): Siliceous and calcareous gravel consisting of granite, limestone, chert, altered volcanic rock (hematitic and silicified), and schist.

Fine (F): Siliceous and calcareous sand consisting of quartzite, quartz, limestone, chert, feldspar, schist, hornblende, granite, graywacke, and hematite-cemented sandstone.

Gradation & Top Size: Evenly graded to a top size of 0.7 in.

Shape & Distribution: CA is rounded to subangular, equidimensional to elongate, and somewhat nonuniformly distributed. FA is rounded to subangular, equidimensional, and uniformly distributed.

PASTE

Color: Medium gray.

Hardness: Moderately hard.

Luster: Subvitreous.

Calcium Hydroxide*: 6 to 8% uniformly distributed small crystals and patches. Calcium hydroxide lines voids and partially coats aggregates.

Unhydrated Portland Cement Clinker Particles (UPC's)*: 10 to 15% uniformly distributed UPC's and relics.

Depth of Carbonation: 0.1 in. from top surface.

Air Content: 3 to 5% uniformly distributed, small, spherical air voids.

Fly Ash*: None observed.

Paste-Aggregate Bond: Moderately tight.

Secondary Deposits: Blades of calcium hydroxide and ettringite needles line or fill voids.

*percent by volume of paste

Microcracking: Microcracks occur around reactive chert particles. Other cracks are randomly oriented and pass through aggregates. Adjacent paste is carbonated.

ESTIMATED WATER-CEMENT RATIO: 0.45 to 0.50.

MISCELLANEOUS: Dark rims occur around chert and dolomitic chert. Adjacent paste is cloudy and isotropic. Curved cracks following the outline of the aggregate are also observed. Gel is seen in one crack and in several voids.

PETROGRAPHIC EXAMINATION OF HARDENED CONCRETE, ASTM C 856

CTL PROJECT NO.: 154070

CLIENT: International Lead Zinc Research Organization

STRUCTURE: Bridge Deck

LOCATION: Ames, Iowa

DATE: January 22, 1992

PROBLEM: Quality Evaluation

EXAMINED BY: L. Powers-Couche

Page 10 of 25

SAMPLE:**Identification:** L14.**Dimensions:** Diameter = 4.0 in.; Length = 5.6 in.**Top Surface:** Moderately abraded surface with coarse aggregates exposed and polished.**Bottom Surface:** Broken surface fractured through aggregates.**Cracks, Joints, Large Voids:** Generally well consolidated with no visible joints. Some underconsolidation occurs around rebar. Air voids are typically smaller than 0.15 in. One side of the core intersected a vertical crack from the top of the core to a depth of 3 in. The crack passes through several coarse aggregate particles.**Reinforcement:** Corroded No. 6 rebar is located 2.5 in. from top of core, and corroded No. 5 or 6 rebar located 3.3 in. from top.**AGGREGATES (A)****Coarse (C):** Siliceous and calcareous gravel consisting of granite, limestone, chert, altered volcanic rock (hematitic and silicified), and schist.**Fine (F):** Siliceous and calcareous sand consisting of quartzite, quartz, limestone, chert, feldspar, schist, hornblende, granite, graywacke, and hematite-cemented sandstone.**Gradation & Top Size:** Evenly graded to a top size of 0.7 in.**Shape & Distribution:** CA is rounded to subangular, equidimensional to elongate, and somewhat nonuniformly distributed. FA is rounded to subangular, equidimensional, and uniformly distributed.**PASTE****Color:** Medium gray.**Hardness:** Moderately hard.**Luster:** Subvitreous.**Calcium Hydroxide*:** 7 to 10% uniformly distributed small crystals.**Unhydrated Portland Cement Clinker Particles (UPC's)*:** 8 to 12% uniformly distributed UPC's and relics.**Depth of Carbonation:** 0.1 in. from top surface.**Air Content:** 4 to 6% uniformly distributed, small, spherical air voids and irregularly shaped, larger (up to 0.5 in.) paste-lined, entrapped air voids.**Fly Ash*:** None observed.**Paste-Aggregate Bond:** Moderately tight. The concrete breaks around the smooth, hard coarse aggregates.

*percent by volume of paste

CTL

Page 11 of 25

Secondary Deposits: Blades of calcium hydroxide and ettringite needles line or fill voids.

Microcracking: Microcracks occur around reactive chert particles. Other cracks are randomly oriented and pass through aggregates. Adjacent paste is carbonated.

ESTIMATED WATER-CEMENT RATIO: 0.50 to 0.55.

MISCELLANEOUS: Dark rims occur around chert and dolomitic chert. Adjacent paste is cloudy and isotropic. Curved cracks following the outline of the aggregate are also observed. Gel is seen in one crack and in several voids.

Table B.2(a): CONCRETE POWDER SAMPLE SUMMARY (1975 CTL Report)

AMES BRIDGE, IOWA

| CTL Powder Designation | Electro-Potential Readings (-MV) | Water-Soluble Chloride Content (lbs/cu yd concrete) | Water-Soluble Chloride Content (by weight of concrete) | Water-Soluble Chloride Content* (by weight of cement) |
|------------------------|-------------------------------------|--|---|--|
| SF2 | | | | |
| 0" TO 1/4" | N.A. | 13.80 | 0.352 | 2.518 |
| 3/4" TO 1" | N.A. | 3.60 | 0.092 | 0.657 |
| 1-1/2" TO 1-3/4" | N.A. | 0.70 | 0.018 | 0.128 |
| SF3 | | | | |
| 0" TO 1/4" | N.A. | 14.50 | 0.370 | 2.646 |
| 3/4" TO 1" | N.A. | 1.40 | 0.036 | 0.255 |
| 1-1/2" TO 1-3/4" | N.A. | 0.70 | 0.018 | 0.128 |
| SF5 | | | | |
| 0" TO 1/4" | N.A. | 4.30 | 0.110 | 0.785 |
| 3/4" TO 1" | N.A. | 1.60 | 0.041 | 0.292 |
| 1-1/2" TO 1-3/4" | N.A. | 0.70 | 0.018 | 0.128 |
| NG1 | | | | |
| 0" TO 1/4" | N.A. | 4.20 | 0.107 | 0.766 |
| 3/4" TO 1" | N.A. | 1.40 | 0.036 | 0.255 |
| 1-1/2" TO 1-3/4" | N.A. | 0.50 | 0.013 | 0.091 |
| NG3 | | | | |
| 0" TO 1/4" | N.A. | 9.00 | 0.230 | 1.642 |
| 3/4" TO 1" | N.A. | 1.30 | 0.033 | 0.237 |
| 1-1/2" TO 1-3/4" | N.A. | 0.50 | 0.013 | 0.091 |
| NG5 | | | | |
| 0" TO 1/4" | N.A. | 3.50 | 0.089 | 0.639 |
| 3/4" TO 1" | N.A. | 1.40 | 0.036 | 0.255 |
| 1-1/2" TO 1-3/4" | N.A. | 0.70 | 0.018 | 0.128 |
| NN2 | | | | |
| 0" TO 1/4" | N.A. | 10.70 | 0.273 | 1.952 |
| 3/4" TO 1" | N.A. | 7.90 | 0.202 | 1.441 |
| 1-1/2" TO 1-3/4" | N.A. | 0.40 | 0.010 | 0.073 |
| NN4 | | | | |
| 0" TO 1/4" | N.A. | 4.20 | 0.107 | 0.766 |
| 3/4" TO 1" | N.A. | 0.80 | 0.020 | 0.146 |
| 1-1/2" TO 1-3/4" | N.A. | 0.40 | 0.010 | 0.073 |
| NN5 | | | | |
| 0" TO 1/4" | N.A. | 2.30 | 0.059 | 0.420 |
| 3/4" TO 1" | N.A. | 0.60 | 0.015 | 0.109 |

* Based on an estimated cement content of 14%
(by weight of cement)

TABLE 8 - RESULTS OF CHLORIDE ANALYSES

| Depth at Which Sample Was Taken | Lbs. Cl ⁻ /cu. yd. of Concrete at Location Indicated | | | | | | | | |
|---------------------------------|---|------|------|-----|------|------|------|------|------|
| | SF2 | SF3 | SF5 | NG1 | NG3 | NG5 | NN2 | NN4 | NN5 |
| 0 - 1/4" | 13.8 | 14.5 | 4.3 | 4.2 | 9.0 | 3.5 | 10.7 | 4.2 | 2.3 |
| 3/4" - 1" | 3.6 | 1.4 | 1.6 | 1.4 | 1.3 | 1.4 | 7.9 | 0.8 | 0.6 |
| 1-1/2" - 1-3/4" | 0.7 | 0.7 | 0.7 | 0.5 | 0.5 | 0.7 | 0.4 | 0.4 | 0.4 |
| 2-1/4" - 2-1/2" | 0.6* | 0.7* | 0.4* | 0.6 | 0.5* | 0.3* | 0.7* | 0.4* | 0.2* |
| 3" - 3-1/4" | 0.6 | 0.5 | 0.5 | -* | - | - | 0.4 | 0.3 | 0.2 |

*Denotes level of top steel at location indicated.

TABLE 9 - RESULTS OF pH MEASUREMENTS

| Depth at Which Sample Was Taken | pH at Location Indicated | | | | | | | | |
|---------------------------------|--------------------------|-------|-------|------|-------|-------|-------|-------|-------|
| | SF2 | SF3 | SF5 | NG1 | NG3 | NG5 | NN2 | NN4 | NN5 |
| 0 - 1/4" | 12.3 | 12.1 | 12.4 | 12.2 | 12.2 | 12.4 | 12.2 | 12.3 | 12.3 |
| 3/4" - 1" | 12.4 | 11.8 | 12.0 | 12.1 | 12.1 | 12.1 | 12.0 | 12.1 | 12.2 |
| 1-1/2" - 1-3/4" | 11.9 | 11.8 | 11.8 | 12.0 | 12.0 | 12.1 | 9.2 | 12.1 | 12.0 |
| 2-1/4" - 2-1/2" | 11.2* | 11.7* | 11.8* | 12.0 | 12.0* | 12.1* | 11.8* | 12.0* | 12.0* |
| 3" - 3-1/4" | 11.3 | 11.8 | 11.9 | -* | - | - | 11.7 | 11.7 | 11.5 |

*Denotes level of top steel at location indicated.




Fig. 21 - Diagram showing cover over top transverse reinforcing bars.




Fig. 22 - Diagram of distribution of electrical potentials in top mat of reinforcing steel.




Fig. 23 - Diagram showing locations of cracks visible at wearing surface.

Table B.2(b): CONCRETE POWDER SAMPLE SUMMARY (1982 CTL Report)

AMES BRIDGE, IOWA

| CTL Powder | | Electro-Potential | Water-Soluble | Water-Soluble | Water-Soluble |
|-------------|---|-------------------|----------------------|-------------------------|-----------------------|
| Designation | | Readings | Chloride Content | Chloride Content | Chloride Content* |
| | | (-MV) | (lbs/cu yd concrete) | (by weight of concrete) | (by weight of cement) |
| LD-1 | M | 90 | 1.44 | 0.037 | 0.263 |
| LD-2 | M | 370 | 0.56 | 0.014 | 0.102 |
| LD-3 | N | 100 | 0.64 | 0.016 | 0.117 |
| LD-4 | S | 350 | 0.88 | 0.022 | 0.161 |
| LD-5 | S | 120 | 0.92 | 0.023 | 0.168 |
| LD-6 | S | 120 | 0.44 | 0.011 | 0.080 |
| LD-7 | S | 240 | 0.20 | 0.005 | 0.036 |
| LD-8 | S | 40 | 0.96 | 0.025 | 0.175 |
| LD-9 | M | 10 | 0.92 | 0.023 | 0.168 |
| LD-10 | S | 110 | 0.64 | 0.016 | 0.117 |
| LD-11 | S | 150 | 0.56 | 0.014 | 0.102 |
| LD-12 | S | 70 | 0.76 | 0.019 | 0.139 |
| LD-13 | M | 80 | 0.40 | 0.010 | 0.073 |
| LD-14 | N | 100 | 0.40 | 0.010 | 0.073 |
| LD-15 | N | 100 | 0.92 | 0.023 | 0.168 |

* Based on an estimated cement content of 14%
(by weight of cement)

Table 1 - Results of Chloride and Metallographic Measurements

| Sample No. | Sample Depth, in. | Steel Mat | Potential-Volts | Cl ⁻ content lbs/cu yd | Average Coating Thickness Remaining Mils * |
|------------|-------------------|---------------|-----------------|-----------------------------------|--|
| LD-1 | 2-1/4 - 2-3/4 | Untreated | -0.09 | 1.44 | - |
| LD-2 | 2 - 2-1/2 | Untreated | -0.37 | 0.56 | - |
| LD-3 | 2 - 2-1/2 | Untreated | -0.10 | 0.64 | - |
| LD-4 | 2-1/4 - 2-3/4 | Galv. & Untr. | -0.35 | 0.88 | 7.7 |
| LD-5 | 2-3/4 - 3-1/4 | Galv. & Untr. | -0.12 | 0.92 | 5.8 |
| LD-6 | 2-1/2 - 3 | Galv. & Untr. | -0.12 | 0.44 | 5.7 |
| LD-7 | 2 - 2-1/2 | Galvanized | -0.24 | 0.20 | - |
| LD-8 | 2 - 2-1/2 | Galvanized | -0.04 | 0.96 | - |
| LD-9 | 2-3/4 - 3-1/4 | Galvanized | -0.01 | 0.92 | - |
| LD-10 | 2 - 2-1/2 | Galvanized | -0.11 | 0.64 | - |
| LD-11 | 2-1/4 - 2-3/4 | Galvanized | -0.15 | 0.56 | 5.4 |
| LD-12 | 2-3/4 - 3-1/4 | Galvanized | +0.07 | 0.76 | - |
| LD-13 | 2 - 2-1/2 | Galvanized | -0.08 | 0.40 | 6.1 |
| LD-14 | 2-1/2 - 3 | Untreated | -0.10 | 0.40 | - |
| LD-15 | 2-1/4 - 2-3/4 | Untreated | -0.10 | 0.92 | - |

*Based on average of 10 readings




Fig. 1 Diagrams of Ames Bridge for Northbound Traffic Showing Results of Potential Measurements, Crack Survey, and Locations of Test Samples.

